



Samphire Hoe Gully Erosion

Top: Badly eroded gully on coastal site

Top right: Initial silt deposits using Hy-Tex CoirLogs

All below: Current level of reinstatement using only Coir-Logs

